

Inspection Photos

10/12/2018

Operator: PDC ENERGY INC - 69175

Location ID: 323128

Inspection Doc. Number: 682504037

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323128



Photo 1: Photo taken from the northeast end of the battery location, facing southwest. Photos 1-2 provide overview of location.



Photo 2: Photo taken from the northeast end of the battery location, facing west

Inspection Photos
Operator: PDC ENERGY INC - 69175
Location ID: 323128



Photo 3: Photo taken from the north end of the location, facing south. Photo shows erosion degradation due to stormwater runoff from the pad. Erosion will need to be repaired, pad will need to be stabilized and BMPs implemented.



Photo 4: Photo taken from the north end of the location, facing south. Photo shows erosion degradation due to stormwater runoff from the pad. Erosion will need to be repaired, pad will need to be stabilized and BMPs implemented.