

Inspection Photos

10/12/2018

Operator: PDC ENERGY INC - 69175

Location ID: 332234

Inspection Doc. Number: 682504039

Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from the northeast end of the former battery location facing southwest. Photo shows surface owner appears to have attempted to re-seed the location back into alfalfa crop. Large areas of the location remain predominantly bare and exposed soil.



Photo 2: Photo taken from the east end of the former battery location facing west. Photo shows surface owner appears to have attempted to re-seed the location back into alfalfa crop. Large areas of the location remain predominantly bare and exposed soil.



Photo 3: Photo taken from the access road, facing west towards the well location



Photo 4: Photo taken from the northeast end of the former well location facing southwest. Photo shows surface owner appears to have attempted to re-seed the location back into alfalfa crop. Large areas of the location remain predominantly bare and exposed soil.



Photo 5: Photo taken from the northeast end of the former well location facing southwest. Photo shows surface owner appears to have attempted to re-seed the location back into alfalfa crop. Large areas of the location remain predominantly bare and exposed soil. 6 foot measuring stick for reference.