

**Inspection Photo
Jewell 22-10
API # 045-09315
Inspection # 689302126**



Location Photo #1



Location Photo #2, unmarked deadman anchor SW edge of location.

**Inspection Photo
Jewell 22-10
API # 045-09315
Inspection # 689302126**



Location Photo #3, Stained rock in battery containment



Location Photo #4, Stained rock in battery containment

**Inspection Photo
Jewell 22-10
API # 045-09315
Inspection # 689302126**



**Location Photo #5, Stained rock in battery
containment**