

Inspection Photo
GMU 28-8C2
API # 045-18725
Inspection # 689302130



Location Photo #1



Location Photo #2

**Inspection Photo
GMU 28-8C2
API # 045-18725
Inspection # 689302130**



Location Photo #3



**Location Photo #4, oily stained rock in
battery containment**

**Inspection Photo
GMU 28-8C2
API # 045-18725
Inspection # 689302130**



Location Photo #5, oily stained rock in battery containment



Location Photo #6, oily stained rock in battery containment

Inspection Photo
GMU 28-8C2
API # 045-18725
Inspection # 689302130



Location Photo #7, oily stained rock in battery containment



Location Photo #8, oily stained rock in battery containment