


Inspection Photos  
Location Name: Fuqua 19-02-10-1H  
API: 05-057-06483



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. No secondary containment around blue barrel.**