

**GM 11-34**  
**Api# 05-045-07419**  
**Inspection # 689701915**



**GM 11-34**  
**Api# 05-045-07419**  
**Inspection # 689701915**



**Sediment build up in ditch.**



**GM 11-34**  
**Api# 05-045-07419**  
**Inspection # 689701915**



**Deep erosion on drainage ditch.**



**GM 11-34**  
**Api# 05-045-07419**  
**Inspection # 689701915**



**Unmarked deadman**