

Letter Sure Release



WELL SITE INSPECTION FORM

3611 Osage St
Denver 80211

~~534-1685~~
693-2626

WELL NAME Bluejay State #1
OPERATOR Terrol Energy
LOCATION NE SW 16-2N-54W
FIELD _____

API NUMBER 05 - 121 - 10337
PERMIT NUMBER _____
COUNTY Washington
INSPECTOR Binkley

AL/PA/DA INSPECTION RESULTS:

PASS(Y) Y FAIL(N) N DATE 8-2-88 FN _____ FD W WO _____

DATE OF INSPECTION BEFORE/DURING DRILLING _____

CASING SIZE _____ DEPTH SET _____ CMT VOL _____ WOC _____
CONSISTENT WITH APD CASING PROGRAM? _____ RETURNS _____
RIG _____ BOP'S _____ CONTACT _____

DATE OF INSPECTION BEFORE/DURING/AFTER COMPLETION _____

PIPE SET? _____ COMPLETION RIG/ACTIVITY _____
DRILLING PITS: CLOSED _____ OPEN _____ WELLHEAD SYSTEM INSTALLED _____
TANK ID: YES _____ NO _____ NA _____ WELL SIGN: YES _____ NO _____
SKIM PIT: _____ gal TANKS: () _____ bbls
EQUIPMENT _____
BRADENHEAD PRESSURE _____ FLUID: NO _____ YES _____ TYPE _____
METER RUN: YES _____ NO _____ WELL STATUS: PR _____ TA _____ SI _____ WELL CAT 3- _____

AL/PA/DA INSPECTION

DATE PLUGGED: 9-30-87 DATE PERMIT EXPIRED: _____
HOLE PLUGGED: YES ✓ NO _____ PITS BACKFILLED: YES _____ NO ✓
MATERIAL BURIED: YES ✓ NO _____ NA _____ SITE CLEAN: YES ✓ NO _____
BOND RELEASE OK: YES ✓ NO ✓ FED _____ HOLE MARKER: YES _____ NO ✓

DATE OF SAFETY/STATUS INSPECTION 8-2-87

COMMENTS R. Pit left open for water?
Location reasonable for terrain. Ad/mig Sage.
See Form 4 pit left open by Gear & recommendation.

Called Mrs Fowler of Victory Oil.

Terry Enright Boulder
Kevin - Geologist Victory Oil 693-2626