

Inspection Photos  
Location Name: Moffat County 2  
API: 05-081-06469



**Photo 1. View of water vapor release from wellhead area of location where inspector was waiting for pumper to arrive.**