

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/17/2018

Submitted Date:

10/17/2018

Document Number:

689701924**FIELD INSPECTION FORM**Loc ID 334689 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285966	WELL	PR	07/31/2006	GW	045-12593	BOSELY SG 314-23	PR
285967	WELL	PR	08/01/2011	GW	045-12592	BOSELY SG 14-23	PR
285968	WELL	PR	07/31/2006	GW	045-12591	BOSELY SG 414-23	PR
285969	WELL	PR	07/31/2006	GW	045-12590	BOSELY SG 514-23	PR
423120	WELL	PR	02/22/2012	GW	045-20678	Bosely SG 544-22	PR
423133	WELL	PR	06/13/2012	GW	045-20679	Bosely SG 44-22	PR
423137	WELL	PR	06/13/2012	GW	045-20680	Bosely SG 444-22	PR
423139	WELL	PR	02/22/2012	GW	045-20681	Bosely SG 344-22	PR
432184	WELL	PR	11/07/2013	GW	045-21931	Bosely SG 702-23-HN1	PR

**General Comment:**

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date	
Type: Ancillary equipment	# 1				
Comment:	Chemical container at wells				
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 10				
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift	#				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 6				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	285966	Type:	WELL	API Number:	045-12593	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285967	Type:	WELL	API Number:	045-12592	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285968	Type:	WELL	API Number:	045-12591	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	285969	Type:	WELL	API Number:	045-12590	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	423120	Type:	WELL	API Number:	045-20678	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	423133	Type:	WELL	API Number:	045-20679	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	423137	Type:	WELL	API Number:	045-20680	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	423139	Type:	WELL	API Number:	045-20681	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

Facility ID:	432184	Type:	WELL	API Number:	045-21931	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: Producing well

Corrective Action:		Date:	
--------------------	--	-------	--

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	
Ditches	Pass					
		Compaction	Pass			
Gravel	Pass					
		Gravel	Pass			
Compaction	Pass					
		Ditches	Pass			
		Culverts	Pass			
Berms	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701925	Inspection 689701924 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615015</a>