

Inspection Photos
Location Name: Foose - 66N64W /18NWSE
Location #: 326915



Photo #1

Foose A18-10 (API # 05-123-13855) wellsite

Weeds

From previous FIR



Photo #2

Foose A18-10 wellsite

Weeds have been cleared

Inspection Photos

Location Name: Foose - 66N64W /18NWSE

Location #: 326915



Photo #3

Foose A18-9, 18-10, 18-23 Battery

From previous FIR

