

Inspection Photos
Location Name: Walker 12-1
API: 05-081-07044



Photo 1. Overview of location taken on perimeter facing north.

Inspection Photos
Location Name: Walker 12-1
API: 05-081-07044



Photo 2. Unmarked risers.



Photo 3. Unmarked riser, wellhead sign knocked over.