

Inspection Photos
Location Name: Quintana 32-6 #15-2
API: 05-067-09096



Secondary containment for chemical container at the #15-4.



Quintana 32-6 #15-2 location photo.

Inspection Photos
Location Name: Quintana 32-6 #15-2
API: 05-067-09096



Perimeter berm is filling with sediment. Wattles are damaged and in disrepair.



Quintana 32-6 #15-2 tank battery.