

Inspection Photos

Location Name: 05-103-07855 (SOUTH DOUGLAS CREEK 7310)

Location ID: 315064

Inspection: 679701398



Location



Tank on side of location. Belongs to Summit.



Inspection Photos

Location Name: 05-103-07855 (SOUTH DOUGLAS CREEK 7310)

Location ID: 315064

Inspection: 679701398



Unmarker deadman. Deadman with steel marker still standing. Cattle are in area.



Small gas leak inside separator building

