

Inspection Photos

Location Name: 05-103-08673 (COORS 8-22)

Location ID: 315538

Inspection: 679701160



Inspection



Unused pipe on ground

Inspection Photos
Location Name: 05-103-08673 (COORS 8-22)
Location ID: 315538
Inspection: 679701160



No bird protector



Sign not updated with new operator