

## Inspection Photos

Location Name: 05-103-08061 (PHILADELPHIA CREEK 13)

Location ID: 315196

Inspection: 679701269

Gas leaking



Location

Gas leaking around threads of cap.



## Inspection Photos

Location Name: 05-103-08061 (PHILADELPHIA CREEK 13)

Location ID: 315196

Inspection: 679701269



**Tank missing labeling. Storm water passing through berm during heavy rainfalls.**



**Missing bird protection on separator stack.**

