

## Inspection Photos

Location Name: 05-103-07431 (SW RANGELY FEDERAL 1-9)

Location ID: 314858

Inspection: 679701320



Location



Well head sign lying on ground, missing "Nearest Public Rd CR 2", and no emergency phone number.



## Inspection Photos

Location Name: 05-103-07431 (SW RANGELY FEDERAL 1-9)

Location ID: 314858

Inspection: 679701320



**Tank currently not in use with no placards or capacity labels.**



**Deadman anchor without marker**

