

Inspection Photos

Location Name: 05-103-08613 (PHILLIPS LUFT 2-31)

Location ID: 315503

Inspection: 679701350



Deadman marker lying on ground



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: 05-103-08613 (PHILLIPS LUFT 2-31)

Location ID: 315503

Inspection: 679701350



Unmarked deadman



Oily waste next to crude oil tank.

Inspection Photos

Location Name: 05-103-08613 (PHILLIPS LUFT 2-31)

Location ID: 315503

Inspection: 679701350



No berm around tank.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources