

Inspection Photos

Location Name: 05-103-08810 (PURDY 2X1)

Location ID: 315609

Inspection: 679701355



Location



Riser uncapped and no lock out tag out