

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2018

Submitted Date:

10/22/2018

Document Number:

687903483**FIELD INSPECTION FORM**Loc ID 451507 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harkins, Liz	303-233-2232/719-429-4513	Lharkins@austinexploration.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451506	WELL	DG	08/25/2017		043-06230	Bird 13-18	DG

General Comment:

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Ancillary equipment	# 1		corrective date
Comment:	Wellhead		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 0		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 451506 Type: WELL API Number: 043-06230 Status: DG Insp. Status: DG**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: On site at 11:00 am. Well set up : Chart Recorder and (COGCC) 1000 psi gauge (Photo). Start chart recorder at 12:15 pm. At 12:22 pm start pressuring up the well. Reached 380 psi at 12:37 pm. Held for 25 minutes till 1:02 pm. NOTE : Wind blew back chart recorder at 12:48 pm, but no change in pressure on 1000 psi gauge. Gauge pressure held at 380 psig. Finish chart recorder at 1:15 pm. Off site at 1:30 pm. Photos of pressure chart.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687903507	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4616614
687903508	Wellhead, chart recorder and gauge	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4616615
687903510	Pressure chart witnessed by John Duran	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4616616
687903511	1 hour pressure chart	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4616617