

# *Inspection Photos*

*Loc#457490*

*Operator: Terra*

*Inspection Number: 692400237*

*Inspection Date: 10/15/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location from top of Cut slope to East.

October 15, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#457490





Photo#2:

View of tracked Cut slope; topsoil pile located above Cut slope.

October 15, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Terra Clough RWF Loc#457490





Photo#3:  
Wattles are installed on location perimeter.

October 15, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#4:

Inspection Photos: Terra Clough RWF Loc#457490