

# *Inspection Photos*

*Loc#334440*

*Operator: Laramie*

*Inspection Number: 692400239*

*Inspection Date: 10/16/2018*





Photo#1:  
Overview of Location from entry to West.

October 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Sup&Shep Loc#334440



Photo#2:  
View of Silt fence installed as perimeter control.

October 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Sup&Shep Loc#334440



**Photo#3:**

Base of Fill slope & windrowed topsoil, where additional BMPs are needed to segregate & prevent mixing & erosion of soils.

October 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Sup&Shep Loc#334440



**Photo#4:**

Base of Fill slope & windrowed topsoil, where additional BMPs are needed to segregate & prevent mixing & erosion of soils.

October 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Sup&Shep Loc#334440



**Photo#5**

Area between base of fill slope & topsoil where erosion & mixing is occurring; overwhelmed Bmp indicated by arrow.

October 16, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Laramie Sup&Shep Loc#334440