

Inspection Photos

API#057-06283

Operator: Apache Corporation

Inspection Number: 692400131

Inspection Date: 9/12/2018





Photo#1:
Overview of Location to East.

September 12, 2018




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Apache Corp PA API#057-06283



Photo#2:

Views of B list noxious weed, Canada thistle established across site. Insert is of Plumeless thistle, another B List noxious weed noted on location.



Photo#3:

Refer to description in Photo#2.



Photo#4:
One piece of casing (pipe) is daylighting on the
NE section of Location.

September 12, 2018



Photo#5:
Refer to description in Photo#4.



Photo#6:

View to Northwest up gully leading down from location. Blue arrow indicates location.

September 12, 2018



Photo#7:

View of erosion and sediment migration occurring in gully leading down from location

September 12, 2018



Photo#8:
Views Southeast along access road, from diversion point area at State boundary, leading up into location.

September 12, 2018



Photo#9:
Refer to description in Photo#8.



Photo#10:
Views along access road, showing erosional issues
and areas devoid of vegetation..

September 12, 2018



Photo#11:
Refer to description in Photo#10.



Photo#12:

Views along access road showing establishment of B list noxious weed, Canada thistle.

September 12, 2018

Photo#13:

Refer to description in Photo#12.




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Apache Corp PA API#057-06283



Photo#14:
Views to West of access road as it exits location.

September 12, 2018



Photo#15:
Refer to description in Photo#14.