

FRAM OPERATING LLC – 10310
API # 05-077-09350 Whiting #26-5
Inspection Date : 10/19/2018



Wellhead with bradenhead valve exposed.



Separator with sign.
Produced water tank in background. No NFPA labels or volumes posted.