

Inspection Photos

Operator: BP Production

API: 05-067-05115

Date: 10/05/2018



Photo 1. View of the project area from the western edge facing northeastward toward the 067-07838 well.



Photo 2. View of vegetation within the central portion of the project area from the western edge facing eastward. Revegetation is comprised of grasses such as intermediate wheatgrass (*Thinopyron intermedium*) and smooth brome (*Bromus inermis*).



Photo 3. View of the project area from the western edge facing southeast toward 067-05115 well. Stormwater controls appear to be recently installed and are largely functioning at this time.





Photo 4. View of what appears to be rig cable and black well pad liner material in the western project area, outside of the fenced working area.



Photo 5. View of the northern portion of the project area from the northeastern corner facing westward.