

Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155



Location Photo #1



Location Photo #2

**Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155**



Location Photo #3



Location Photo #4, Missing sign information

**Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155**



Location Photo #5, unused equipment.



**Location Photo #6, stained oily material in
containment battery.**

**Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155**



Location Photo #7, unmarked flow lines



Location Photo #8, unmarked flow lines

**Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155**



Location Photo #9, unmarked flow lines



Location Photo #10, unmarked flow lines

**Inspection Photo
Miller23B-36-692
API # 045-12499
Inspection # 689302155**



Location Photo #11, unmarked flow lines



Location Photo #12, unmarked flow lines