Inspector N	lame: GINTAUTAS	3, PETER							
FORM		Ş	State of Col	orado		D N R	-	ion Date:	
INSP	Oil	and Gas	Conserva f	tion Commis				0/23/2018	
Rev X/15		1120 Lincoln S			ed Date:				
			(303) 894-2100 Fax		(TM		<u>0/24/2018</u>	
		FIELD	DINSPECT	ION FORM					ent Number: <u>78302216</u>
Loc ID	Inspector Na	ame:	On-Site I	Inspection			Summary:		
331990	GINTAUTAS	S, PETER	2A	A Doc Num:		_ 🔲 ТНІ	IS IS A FOLLOW UP	INSPECT	ION
Operator I	nformation:					FOI	LLOW UP INSPECTION	ON REQL	JIRED
OGCC Op	erator Number:	47120				NO NO	FOLLOW UP INSPE	CTION R	EQUIRED
Name of O	perator: KERR M		 & GAS ONSHC	DRE LP		Finding	<u>gs:</u>		
Addross	P O BOX 173779					5	_Number of Commen	ts	
Address.	F O BOX 173779					1	_Number of Corrective	e Actions	
City:	DENVER	State:	CO	Zip: 802	17-	X Corr	rective Action Response	Requested	d
						PR	Y CORRECTIVE ACT EVIOUS INSPECTIO EN ADDRESSED AR	NS THÀT	HAVE NOT
Contact In	formation:								
Contact N	lame	Phor	ne	Email		C	comment		
,						A	II Inspections		
				COGCCinsper o.com	ctions@ar				
Inspected	Facilities:								
Facility ID	Туре	Status	Status Date	Well Class	API Nur	m	Facility Name		Insp Status
458282	TANK BATTERY	AC	10/23/2018		-		Harkis 41-13 battery	'	EI
General C	omment:	<u> </u>						I	
battery ar	nd well it serves no	ot colocated	l. battery inspe	ction in this docu	ment				

Inspector Name: GINTAUTAS, PETER

			Location		
Overall Good: 😿					
Signs/Marker:					
Туре	BATTERY				
Comment:					
Corrective Action:		Date	:		
Type	TANK LABELS/PLACARE)S			
Comment:					
Corrective Action:	Date	: <u>12/24/2018</u>			
Emergency Contact N	lumber:				
Comment:					
Corrective Action:				Date:	
Overall Good: 🔀					
Spills:	1				
-	•			_	
Туре	Area	Volume			
In Containment: N	lo				
Comment: n	o spills observed a surface	e during inspe	ection		
Multilple Spills a	Ind Releases?				
Fencing/:					
Type	IGNITOR/COMBUSTOR				
Comment:					
Corrective Action:				Date:	
	TANK BATTERY				
Comment:					
Corrective Action:				Date:	
				Date.	
	SEPARATOR				
Comment:					
Corrective Action:				Date:	
Equipment:					corrective date
Type: Gas Meter Run		1			
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heat	ted Separator # 7	1			
Comment:	earthen berm				
Corrective Action:	Date:				
Type: Horizontal Heat	ted Separator # '	1			
Comment:					
Commond.					
Corrective Action:				Date:	

Inspector Name: GINTAUTAS, PETER

Commer	nt:									
Corrective Actio	n:								Date:	
Tanks and Berms:										
Contents # Capacity Type Tank ID SE GPS										
CRUDE OIL		1	300 BBL	S	STEEL AST			,		
Comm	ent:				I					
Corrective Ac	tion:								Date	:
Paint										
Condition Adeq	uate									
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Туре	Capacity			Peri	meability (Wall)	Permeability	ermeability (Base)		Maintenance	
Earth	Adequate)		Wal	Is Sufficent			Adequate		
Comment:										•
Corrective Action:									Date	:
Contents		#	Capacity	,	Туре		Tank ID	SE GPS		
PRODUCED WATER 1 <100 BBLS										
Comm	ient:									
Corrective Ac	tion:								Date	:
Paint	·								·	
Condition										
Other (Content)										
Other (Capacity)										
Other (Type)										
<u>Berms</u>										
Туре	Capacity			Peri	meability (Wall)	Permeability	(Base)	Maintenance	Э	
Earth	Adequate)		Wal	Is Sufficent			Adequate	_	
Comment:	shared be	erm	with crude	e tan	k					
Corrective Action:									Date	:
<u>Venting:</u>										
Yes/No)									
Comment	:									
Corrective Action									Date:	
<u>Flaring:</u>										
Туре										
Commen										
Corrective Actior	1:								Date:	

				Inspected F	acilities				
acility ID:	458282	Туре:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI