

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2018

Submitted Date:

10/24/2018

Document Number:

692600626**FIELD INSPECTION FORM**

Loc ID 413590 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-----------------------------|---------|
| Jones, Greg | (970) 630-3909 | greg.jones@ownresources.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 411882 | WELL | PR | 04/23/2010 | GW | 125-11697 | MILLER 13-17 1N44W | PR |

General Comment:Routine Inspection

Location

| | | | |
|--------------------|-----------------------------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|----------------------------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign mounted to fence | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Lease sign mounted to meter shed | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|---|-------|--|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence around entire location | | |
| Corrective Action: | | Date: | |
| Type | OTHER | | |
| Comment: | Metal panels around meter shed and metal shed | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Metal panels around wellhead | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | Meter run in metal shed on east side of location | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|--------------------------------------|-------|--|
| Type: Vertical Separator | # 1 | | |
| Comment: | Vertical gas separator in metal shed | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 411882 | Type: | WELL | API Number: | 125-11697 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Producing. Casing production | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Gravel | Pass | | | |

Comment: Location is grassed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT