

Inspection Photos  
Location Name: Grant Properties LTD #1  
Location ID: 32008



Photo 1 WH Trash around WH



Photo 2 TNK BTRY Pro tank faded placards and no volume sign



**Inspection Photos**  
**Location Name: Grant Properties LTD #1**  
**Location ID: 32008**



Colorado Oil and Gas Conservation Commission  
39.90806, -104.14265, 1473.1m  
Oct 24, 2018 09:16:26

**Photo 5 Stained soil in side sep house**



Colorado Oil and Gas Conservation Commission  
39.90798, -104.14282, 1468.9m  
Oct 24, 2018 09:17:26

**Photo 6 Weeds around sep**

**Inspection Photos**  
**Location Name: Grant Properties LTD #1**  
**Location ID: 32008**



**Photo 7 Weeds around TNK BTRY**



**Photo 8 Tank volume and label not legible**