

## Inspection Photos

Location Name: 05-103-08095 (TRAIL CANYON 31-2)

Location ID: 315220

Inspection: 679701468



location



Separator venting to tank during first 5 minutes while inspector on location.

