

## Inspection Photos

Location Name: 05-103-07923 (UNIVERSAL 2-19)

Location ID: 315104

Inspection: 679701472



location



Weeds in pit

## Inspection Photos

Location Name: 05-103-07923 (UNIVERSAL 2-19)

Location ID: 315104

Inspection: 679701472



Sign missing "Nearest Public Rd CR 27"



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources