

Inspection Photos

Location Name: 05-103-08038 (CONTINENTAL 1-20)

Location ID: 315182

Inspection: 679701478



location



Weeds next to separator and in pit

Inspection Photos

Location Name: 05-103-08038 (CONTINENTAL 1-20)

Location ID: 315182

Inspection: 679701478



Well sign lying on ground



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources