

Inspection Photos

Location Name: 05-103-07922 (UNIVERSAL 1-19)

Location ID: 315103

Inspection: 679701486



location



Casing valve at well head leaking gas

Inspection Photos

Location Name: 05-103-07922 (UNIVERSAL 1-19)

Location ID: 315103

Inspection: 679701486



Weeds next to separator



Weeds in separator pit

