



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Reclamation Tablet (reclamationtablet)
Submission Date: Oct 19, 2018 3:01:47 PM MDT
Server Receive Date: Oct 19, 2018 3:02:22 PM MDT
Reference Number: 20181019-1889811866
Location: 557 Airpark Dr, Durango, CO 81303, USA
Oct 19, 2018 3:01:44 PM MDT [[View Map](#)]

Information

Name: reclamationtablet
Date: Oct 19, 2018
Well Name: PAYNE, EVELYN GAS UNIT F 1
API Number: 50670706900
Select State: Colorado
Work type: COGCC Inspection AR
Action Complete: Other

Picture North to South



Picture South to North



Picture East to West



Picture West to East



Completed work description

treated weeds within the project area.