

**Inspection Photo
Pitman 18-7D
API # 045-09148
Inspection # 689302192**



Location Photo #1



Location Photo #3, Sediment being moved off location, Repair with BMP's

**Inspection Photo
Pitman 18-7D
API # 045-09148
Inspection # 689302192**



Location Photo #3, Sediment being moved off location, Repair with BMP's



Location Photo #4, Sediment being moved off location, Repair with BMP's

**Inspection Photo
Pitman 18-7D
API # 045-09148
Inspection # 689302192**



Location Photo #5, Sediment being moved off location, Repair with BMP's

