

**Inspection Photo
Couey 17-4
API # 045-07366
Inspection # 689302196**



Location Photo #1



**Location Photo #2, Storm water draining
into holes along the ditch.**

**Inspection Photo
Couey 17-4
API # 045-07366
Inspection # 689302196**



Location Photo #3, Storm water draining into holes along the ditch.



Location Photo #4, Storm water draining into holes along the ditch.

**Inspection Photo
Couey 17-4
API # 045-07366
Inspection # 689302196**



Location Photo #5, Storm water draining into holes along the ditch.



Location Photo #6, Storm water draining into holes along the ditch.