

**Inspection Photo
Couey 17-5B
API # 045-07792
Inspection # 689302198**




Location Photo #1



Location Photo #2, unmarked anchor near separator

**Inspection Photo
Couey 17-5B
API # 045-07792
Inspection # 689302198**



Location Photo #3, unmarked anchor near separator



Location Photo #4, 2 Master valves near wellheads.

**Inspection Photo
Couey 17-5B
API # 045-07792
Inspection # 689302198**



Location Photo #5, poly line on East side of location in rabbit brush

Location Photo #6, Hole on edge of location , East side