

Inspection Photos
Location Name: Elaine 41-18
Location ID: 320103



Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: Elaine 41-18
Location ID: 320103



Colorado Oil and Gas Conservation Commission
39.9701, -104.58646, 1546.2m
Oct 25, 2018 11:54:35



Colorado Oil and Gas Conservation Commission
39.97011, -104.58646, 1546.3m
Oct 25, 2018 11:54:46

Photo 3 Trash in sep building

Photo 4 Ceiling falling down on equipment and trash

Inspection Photos
Location Name: Elaine 41-18
Location ID: 320103



Colorado Oil and Gas Conservation Commission
39.97011, -104.58646, 1546.3m
Oct 25, 2018 11:54:59

Photo 5 Ceiling falling down and trash on equipment