

Inspection Photos
Location Name: Hosmer #21-32
Location ID: 320079



Photo 1 WH

Photo 2 PU motor laying on ground belt guard off

Inspection Photos
Location Name: Hosmer #21-32
Location ID: 320079



Photo 3 roof blown off sep house

Photo 4 Sep roof laying on ground