

**Inspection Photos**  
**Location Name: Hosmer #43-32**  
**Location ID: 320289**



**Photo 1 TNK BTRY**



**Photo 2 WH PU disconnected plunger lift installed  
PU unused equipment**

**Inspection Photos**  
**Location Name: Hosmer #43-32**  
**Location ID: 320289**



**Photo 3 Trash and unused equipment**

**Photo 4 Unused equipment**

**Inspection Photos**  
**Location Name: Hosmer #43-32**  
**Location ID: 320289**



**Photo 5 Trash and unused equipment**



**Photo 6 TNK BTRY pic**