

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/25/2018

Submitted Date:

10/25/2018

Document Number:

688302815**FIELD INSPECTION FORM**
 Loc ID 455198 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26580Name of Operator: BURLINGTON RESOURCES OIL & GAS LPAddress: 600 N DAIRY ASHFORD RDCity: HOUSTON State: TX Zip: 77079**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
ConocoPhillips		COPColoradoReg@conocophillips.com	
Yu, Liang	281-467-5712	Liang.Yu@conocophillips.com	Regulatory Coordinator

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455195	WELL	DG	10/03/2018		005-07366	Chico 4-65 26-25 2BH	DG

General Comment:

Drilling Inspection.
Multiwell pad

LocationOverall Good: ☒**Signs/Marker:**

Type	OTHER		
Comment:	location sign at gate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	855-595-8258	
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:

Type: Flare	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 455195 Type: WELL API Number: 005-07366 Status: DG Insp. Status: DG**Well Drilling**

Rig: Rig Name: Nabors B16 Pusher/Rig Manager: Jason Beach
Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydri Type: _____
Pressure Test BOP: Pass Test Pressure PSI: 5000 Safety Plan: YES

Drill Fluids**Management:**

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
Multi-Well: _____ Disposal Location: _____

Comment: 10/24/2018 Shell test on wellhead 250/5000 psi and mudlines 6000 psi

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Mulching	Pass	Mulching	Pass			
Gravel	Pass	Gravel	Pass	Covering Materials	Pass	
Seeding	Pass	Seeding	Pass			
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
Waddles	Pass	Waddles	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302818	ConocoPhillips Chico sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4621902