

Inspection Photos

Location Name: Schroeder-66N64W /23NESW

Location #: 305375



Photo #1

Schroeder 23-31 (API # 05-123-22881) wellsite

P&A'd | Wellhead NOT cut & capped

Unused Equipment on site



Photo #2

Schroeder 23-33, 23-31 Battery

All Equipment is Shut-down & Unused

2 wells have been P&A'd.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources