

## Inspection Photos

Location Name: Peppler-66N64W /24NWSW

Location #: 310298



**Photo #1**

**Peppler 24-32 (API # 05-123-26192) wellsite**

**P&A'd | Wellhead NOT cut & capped**

**Unused Equipment on site**



**Photo #2**

**Peppler 24-32 Battery**

**All Equipment is Shut-down & Unused**

**Well has been P&A'd.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources