

Inspection Photos

Location Name: 05-103-10703 (RG 24-20-398)

Location ID: 316516

Inspection: 679701520



location



Dead bird in Methanol secondary containment. Unknown if bird died before or after last attempt to fill in gap with wire.

Inspection Photos

Location Name: 05-103-10703 (RG 24-20-398)

Location ID: 316516

Inspection: 679701520



Tanks missing "300" on capacity.

