

Inspection Photos

Operator: BP Production

API: 05-067-07025

Date: 10/16/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing within the interim reclamation areas with grasses such as sand dropseed (*Sporobolus airoides*) and western wheatgrass (*Pascopyrum smithii*).



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of Russian knapweeds (*Acroptilon repens*) within the southwestern project area. Approximately 10 individuals observed.