

Inspection Photos

Operator: BP Production

API: 05-067-06684

Date: 10/16/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is progressing with grasses such as sand dropseed (*Sporobolus airoides*) and western wheatgrass (*Pascopyrum smithii*).





Photo 3. View of the northern project area from the northwestern corner facing eastward. Kochia debris needs to be removed



Photos 4-6. View of junk and debris within the interim reclamation area.