

Inspection Photos

Operator: BP Production

API: 05-067-07087

Date: 10/16/2018



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing southeastward. Revegetation is progressing with a mixture of grasses such as intermediate wheatgrass (*Thinopyron intermedium*), sedges (*Carex* spp.), and cattails (*Typha* sp.)





Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of northern project area from the northeastern corner facing westward.



Photo 5. View of anchor marker that is broken and needs to be replaced.



Photo 6. View of Canada thistles (*Cirsium arvense*) within the southeastern project area. Approximately 500 individuals observed in this portion of the project area.