

**Inspection Photo
GGU 3-29
API # 045-07152
Inspection # 689302226**



Location Photo #1



Location Photo #2

**Inspection Photo
GGU 3-29
API # 045-07152
Inspection # 689302226**



Location Photo #3, unused equipment



Location Photo #4, Missing information on battery sign

**Inspection Photo
GGU 3-29
API # 045-07152
Inspection # 689302226**



Location Photo #5, unmarked deadman by fence