

**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



Location Photo #1



Location Photo #2

**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



Location Photo #3



Location Photo #4, Missing access road information on battery sign.

**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



Location Photo #5, dripping fitting on flowline



Location Photo #6, oil stain on ground



**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



**Location Photo #7, unused equipment on
East end of Separators**



**Location Photo #8, unused hose section by
battery stairs**

**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



**Location Photo #9, unmarked deadman on
South side of location**



**Location Photo #10, unmarked deadman on
South side of location**

**Inspection Photo
GGU Federal 41A
API # 045-19806
Inspection # 689302230**



Location Photo #11, unmarked deadman in SE corner of location.



Location Photo #12, unmarked deadman East of Combuster.