

# HALLIBURTON

iCem<sup>®</sup> Service

## **NOBLE ENERGY INC - EBUS**

Date: Monday, September 10, 2018

## **Emmy State H25-764 Production**

Job Date: Wednesday, August 15, 2018

Sincerely,  
Adam McKay

## Legal Notice

---

### Disclaimer:

All information in this report is provided subject to the terms and conditions which govern the services provided by Halliburton. Halliburton personnel use their best efforts in gathering information and their best judgment in interpreting it, but any interpretation, research, analysis or recommendation furnished by Halliburton are opinions based upon inferences from measurements and empirical relationships and assumptions, which inferences and empirical relationships and assumptions are not infallible, and with respect to which professionals in the industry may differ. iCem 3D Displacement results are used to understand how fluids intermix during a cement job. Simulation and 3D displacement results are not intended as and should not be used as a replacement for bond logs in determining top of cement. Current 3D model calculations are known to model more volume than the input volume for standard cases due to known calculation improvements required. For rotational cases, the modeled volume will be impacted by the same calculations impacting the standard cases, as well as additional constraints imposed to make the calculation time required operationally feasible. Therefore, until further notice, 3D displacement results should not be used for replacement of a bond log, or used as an identifier of top of cement. HALLIBURTON IS UNABLE TO GUARANTEE THE ACCURACY OF ANY CHART INTERPRETATION, RESEARCH ANALYSIS, OR JOB RECOMMENDATION and any interpretation or recommendation is not for use of or reliance upon by any third party. The customer has full responsibility for any of its decisions which are based on the information provided in this report.

## Table of Contents

---

1.0	Cementing Job Summary .....	4
1.1	Executive Summary .....	4
2.0	Real-Time Job Summary .....	7
2.1	Job Event Log .....	7
3.0	Attachments.....	10
3.1	Cement Job With Events.png.....	10

## 1.0 Cementing Job Summary

---

### 1.1 Executive Summary

---

Halliburton appreciates the opportunity to perform the cementing services on the **Emmy State H25-764** cement **Production** casing job. A pre-job safety meeting was held before the job where details of the job were discussed, potential safety hazards were reviewed, and environmental compliance procedures were outlined.

Halliburton maintains a continuous quality improvement process and appreciates any comments or suggestions that you may have. Halliburton again thanks you for the opportunity to perform service work on this well. We hope to be your solutions provider for future projects.

Respectfully,

**Halliburton [Ft. Lupton]**

*The Road to Excellence Starts with Safety*

<b>Sold To #:</b> 345242		<b>Ship To #:</b> 3883737		<b>Quote #:</b>		<b>Sales Order #:</b> 0905061836	
<b>Customer:</b> NOBLE ENERGY INC-EBUS				<b>Customer Rep:</b> John Drahota/Chris Ewing			
<b>Well Name:</b> EMMY STATE			<b>Well #:</b> H25-764		<b>API/UWI #:</b> 05-123-46973-00		
<b>Field:</b> WATTENBERG		<b>City (SAP):</b> KEENESBURG		<b>County/Parish:</b> WELD		<b>State:</b> COLORADO	
<b>Legal Description:</b> SE SW-25-3N-65W-285FSL-1230FWL							
<b>Contractor:</b> H & P DRLG				<b>Rig/Platform Name/Num:</b> H & P 517			
<b>Job BOM:</b> 7523 7523							
<b>Well Type:</b> HORIZONTAL OIL							
<b>Sales Person:</b> HALAMERICA\HB70026				<b>Srvc Supervisor:</b> Nick Cummins/Kamereon White			
<b>Job</b>							

<b>Formation Name</b>			
<b>Formation Depth (MD)</b>		<b>Top</b>	<b>Bottom</b>
<b>Form Type</b>		BHST 230 degF	
<b>Job depth MD</b>		17479ft	<b>Job Depth TVD</b> 7017ft
<b>Water Depth</b>		<b>Wk Ht Above Floor</b> 5ft	
<b>Perforation Depth (MD)</b>		<b>From</b>	<b>To</b>

Well Data										
Description	New / Used	Size in	ID in	Weight lbm/ft	Thread	Grade	Top MD ft	Bottom MD ft	Top TVD ft	Bottom TVD ft
Casing		9.625	8.921	36			0	1936	0	1936
Casing		5.5	4.778	20			0	17479	0	7017
Open Hole Section			8.5				2485	6680	1361	6680
Open Hole Section			8.5				6680	17494	6680	7018

Tools and Accessories									
Type	Size in	Qty	Make	Depth ft		Type	Size in	Qty	Make
<b>Guide Shoe</b>	5.5	1	HES	17479		<b>Top Plug</b>	5.5	1	HES
						<b>Bottom Plug</b>	5.5	2	HES
<b>Float Collar</b>	5.5	1	HES	17433					

Fluid Data									
Stage/Plug #: 1									
Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal
1	11.5 lb/gal Tuned Spacer III	Tuned Spacer III	120	bbl	11.5	3.78		5	23.5

Fluid #	Stage Type	Fluid Name	Qty	Qty UoM	Mixing Density lbm/gal	Yield ft3/sack	Mix Fluid Gal	Rate bbl/min	Total Mix Fluid Gal	
2	ElastiCem	ELASTICEM (TM) SYSTEM	140	sack	13.2	1.68		5	8.04	
3	ElastiCem w/ SCBL	ELASTICEM (TM) SYSTEM	430	sack	13.2	1.68		8	8.06	
4	NeoCem NT1	NeoCem TM	1217	sack	13.2	2.04		8	9.75	
5	Displacement	Displacement	387	bbl	8.33			10		
Cement Left In Pipe		Amount	45 ft		Reason			Shoe Joint		
Mix Water:		pH 7	Mix Water Chloride:		<400 ppm		Mix Water Temperature:			74°F
			Plug Displaced by:		8.33 lb/gal		Disp. Temperature:			
Plug Bumped?		Yes	Bump Pressure:		1900 psi		Floats Held?			Yes
Cement Returns:		0	Returns Density:		11.5 lb/gal					
Comment										

## 2.0 Real-Time Job Summary

### 2.1 Job Event Log

Type	Seq. No.	Activity	Graph Label	Date	Time	Source	DS Pump Press <i>(psi)</i>	DH Density <i>(ppg)</i>	Comb Pump Rate <i>(bbl/min)</i>	Comments
Event	1	Call Out	Call Out	8/15/2018	06:30:00	USER				The crew was called out for an on location time of 1200.
Event	2	Depart from Service Center or Other Site	Depart from Service Center or Other Site	8/15/2018	10:50:00	USER				The crew held a pre journey safety meeting. The supervisor called in a journey. The crew departed from the service center.
Event	3	Arrive at Location from Service Center	Arrive at Location from Service Center	8/15/2018	11:30:00	USER				The crew arrived on location safely. The rig was still running casing. The supervisor went and got numbers from the company man. TD 17,494' TP 17,479' 5 1/2" 20# P-110 FC 17,433' PC 1,936' 9 5/8" 36# J-55 TVD 7,017' OH 8 1/2" Mud 9.6 ppg
Event	4	Assessment Of Location Safety Meeting	Assessment Of Location Safety Meeting	8/15/2018	11:40:00	USER				Crew discussed all hazards and procedures for spotting trucks in.
Event	5	Pre-Rig Up Safety Meeting	Pre-Rig Up Safety Meeting	8/15/2018	11:45:00	USER				Crew discussed rig up hazards and rig up procedure.
Event	6	Other	Rig Up Equipment	8/15/2018	11:50:00	USER				Rigged up all HES equipment and lines.
Event	7	Prime Pumps	Prime Pumps	8/15/2018	13:51:46	COM4				
Event	8	Other	Rig Up Completed	8/15/2018	14:00:00	USER				Rig up completed no one got hurt.
Event	9	Casing on Bottom	Casing on Bottom	8/15/2018	14:35:00	USER				Casing on bottom
Event	10	Safety Meeting - Pre Job	Safety Meeting - Pre Job	8/15/2018	16:30:00	USER				Crew discussed all hazards and the procedure for cement job, with all parties involved.
Event	11	Check Weight	Check Weight	8/15/2018	16:35:42	COM4				
Event	12	Other	Fill Lines	8/15/2018	16:39:15	COM4				We filled lines with 3 bbls of water. At 3 bpm with 250 psi.
Event	13	Test Lines	Test Lines	8/15/2018	16:42:05	COM4	2940.00	8.40		We pressure tested the rigs IBOP to 3,000 psi. The pressure test passed.
Event	14	Test Lines	Test Lines	8/15/2018	16:47:34	COM4	4761.00	8.48		We tested all HES lines to 4500 psi. The pressure test passed.
Event	15	Drop Bottom Plug	Drop Bottom Plug	8/15/2018	16:51:00	COM4				The company man witnessed the first bottom plug drop.

Event	16	Pump Spacer 1	Pump Spacer 1	8/15/2018	16:51:13	COM4	431.00	11.76	4.00	We pumped 120 bbls of spacer at 5 bpm. At 11.5 ppg 3.78 yield 23.5 gals/sk. We verified weight using pressurized mud scales. 5 bpm with 490 psi. Top of spacer is 0'.
Event	17	Shutdown	Shutdown	8/15/2018	17:15:30	COM4				Shutdown to drop second bottom plug.
Event	18	Drop Bottom Plug	Drop Bottom Plug	8/15/2018	17:18:46	COM4				Company man witnessed the second bottom plug drop.
Event	19	Pump Cap Cement	Pump Cap Cement	8/15/2018	17:18:56	COM4	227.00	13.10	4.00	We pumped 42 bbls (140 sks) of cap cement. At 13.2 ppg 1.68 yield 8.04 gals/sk. We verified weight using pressurized scales. Estimated top of cap cement is 2,504'.
Event	20	Check Weight	Check Weight	8/15/2018	17:21:39	COM4	190.00	13.12	4.10	We checked the weight of the cap cement using pressurized scales it weighed up at 13.2 ppg.
Event	21	Pump Lead Cement	Pump Lead Cement	8/15/2018	17:28:10	COM4	559.00	13.22	8.00	We pumped 128 bbls (430 sks) of lead cement. At 13.2 ppg 1.68 yield 8.06 gals/sk. We verified weight using pressurized scales. Estimated top of lead cement is 3,531'.
Event	22	Check Weight	Check Weight	8/15/2018	17:32:01	COM4	593.00	13.44	8.00	We checked the weight of the lead cement using pressurized scales it weighed up at 13.2 ppg.
Event	23	Pump Tail Cement	Pump Tail Cement	8/15/2018	17:50:27	COM4	283.00	13.13	5.00	We pumped 442 bbls (1217 sks) of tail cement. At 13.2 ppg 2.04 yield 9.75 gals/sk. We verified weight using pressurized scales. Estimated top of tail cement is 6,666.5'.
Event	24	Check Weight	Check Weight	8/15/2018	17:51:23	COM4	457.00	13.17	6.00	We checked the weight of the tail cement using pressurized scales it weighed up at 13.2 ppg.
Event	25	Check Weight	Check Weight	8/15/2018	18:00:39	COM4	820.00	13.09	8.00	We checked the weight of the tail cement using pressurized scales it weighed up at 13.2 ppg.
Event	26	Check Weight	Check Weight	8/15/2018	18:26:35	COM4	821.00	13.21	8.00	We checked the weight of the tail cement using pressurized scales it weighed up at 13.2 ppg.
Event	27	Pump Shoe Cement	Pump Shoe Cement	8/15/2018	18:49:51	COM4	314.00	13.35	4.00	We pumped a 13.4 ppg shoe.
Event	28	Shutdown	Shutdown	8/15/2018	18:50:13	COM4				Shutdown to wash pumps and lines.
Event	29	Drop Top Plug	Drop Top Plug	8/15/2018	19:05:26	COM4				Company man witnessed top plug drop.
Event	30	Pump Displacement	Pump Displacement	8/15/2018	19:05:30	COM4	626.00	8.33	10.00	We pumped 387 bbls of water. The first 20 bbls with MMCR. We put biocide throughout till the last 30 bbls to make sure the lines had fresh water in them for rig down. We got 0 bbls of spacer to surface

Event	31	Displ Reached Cement	Displ Reached Cement	8/15/2018	19:08:30	COM4	626.00	8.06	10.00	Displacement reached cement at 30 bbls away.
Event	32	Bump Plug	Bump Plug	8/15/2018	19:48:54	COM4	1904.00	8.13	2.90	we bumped the plug the final circulating pressure was 1,900 psi. We brought it 500 psi over to 2,600 psi.
Event	33	Other	Check Floats	8/15/2018	19:55:13	COM4				We checked floats the floats held. We got 5 bbls back to the truck
Event	34	End Job	End Job	8/15/2018	19:58:20	COM4				Cement job complete.
Event	35	Post-Job Safety Meeting (Pre Rig-Down)	Post-Job Safety Meeting (Pre Rig-Down)	8/15/2018	20:00:00	USER				Crew discussed rig down hazards and rig down procedure.
Event	36	Rig Down Lines	Rig Down Lines	8/15/2018	20:05:00	USER				Rigged down all HES equipment and lines.
Event	37	Rig-Down Completed	Rig-Down Completed	8/15/2018	20:45:00	USER				Rig down completed no one got hurt.
Event	38	Depart Location for Service Center or Other Site	Depart Location for Service Center or Other Site	8/15/2018	21:30:00	USER				The crew held a pre journey safety meeting. The supervisor called in a journey. The crew departed from location.

3.0 Attachments

3.1 Cement Job With Events.png

