

# Final Reclamation Inspection

October 25, 2018

Operator: CARRIZO OIL & GAS INC - #10338

API: 05-123-38592

Inspection Document #: 682404103

Weld County, CO

SWNW Section 29 T8N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

## Inspection Photos

Location Name: Gaffney #4-29-8-61

API: 05-123-38592



**Photo 1.** Photo taken of the active well at the location. This inspection confirms that only one well was drilled; therefore, this will be a well release on an active location.